

The DCSA Series is a loop-powered, linear output current transducer that provides an output that is directly proportional to the RMS AC current passing through the LCSC10T12 sensor. The DCSA provides either an analog current or voltage: 4 - 20 mA, 1 to 5VDC, or 2 to 10VDC. Each unit is factory calibrated for monitoring (with the LCSC10T12 connected) in one of four ranges; 0 - 5, 0 - 10, 0 - 20, or 0 - 50A. Zero and span adjustments allow field calibration if needed. The DCSA mounts on both DIN 1 and DIN 3 rails.

For more information see:

Appendix B, page 166, Figure 22 for dimensional drawing. Appendix C, page 169, Figure 21 for connection diagram.

### **Features:**

- Mounts on DIN 1 or DIN 3 rail
- 0 50A in 4 ranges using LCSC10T12 sensor
- Loop powered from 10 to 30VDC
- Linear output from 4 20mA, 1 10VD
- Zero & span adjustments
- Separate sensor & control unit

Approvals: (E \$\square\$)

## **Auxiliary Products:**

• Current sensor: P/N: LCSC10T12


### **Available Models:**

DCSA50 LCSC10T12

If desired part number is not listed, please call us to see if it is technically possible to build.

#### Operation

The DCSA varies the effective resistance of its output in direct proportion to the current flowing in the conductor monitored by the LCSC10T12. Connecting the power supply to terminals C & D provides a 4 to 20mA DC current. Connect the power supply to terminals C & A to get 1 to 5VDC at terminal D. Connect the power supply to terminals C & B to get 2 to 10VDC at terminal D.



## Order Table:

Current Range	DCSA Input Range	<u>Part</u>
with LCSC10T12	(F to E)	Number
0-5A	0-5mA AC	DCSA5
0-10A	0-10mA AC	DCSA10
0-20A	0-20mA AC	DCSA20
0-50A	0-50mA AC	DCSA50

Specifications


pecifications	
Input	
Ranges (without LCSC10T12 connected)	
4 factory calibrated ranges in mA AC	0 - 5mA, 0 - 10mA, 0 - 20mA, or 0 - 50mA AC
Factory calibration	±0.5% of full scale
Repeat Accuracy	±0.25% of full scale under fixed conditions
Response Time	≅ 300ms
Temperature Coefficient	±0.05%/°C
Input To Output	Not isolated
Output	
Type Analog	
Range	4 - 20mA, or 1 to 5VDC or 2 to 10VDC
Supply Voltage*	10 to 30VDC
Momentary Voltage	40VDC for 1m
Zero Adjust	≅ 3.75 - 4.25mA
Span Adjust	18mA - 22mA
Adjustment	Mini-screw, multi-turn potentiometer
Protection	
Dielectric Breakdown	≥ 2500V RMS terminals to mounting surface
Insulation Resistance	≥ 100 MΩ
Polarity	Units are reverse polarity protected

Toroidal Current Sensor LCSC10T12


Mechanical
Mounting DIN 1 & DIN 3 rail mounting
Termination Wire clamp For 22 - 14AWG (.336 mm <sup>2</sup> 2.5 mm <sup>2</sup> )
Environmental
Operating / Storage Temperature30° to 60°C / -40° to 85°C
Humidity95% relative, non-condensing
Weight
Accessory - LCSC10T12 Toroidal Sensor
Number of Turns
Nominal Output Current Full Range 0 - 50 mA
Maximum Allowable Current Steady 50A turns
Inrush 300A turns for 10s
Burden≤ 0.5 VA
Frequency 0 - 20A / 21 - 50A 20/100 Hz / 30/100 Hz
Sensor Hole
(21.1 mm <sup>2</sup> ) THHN wire
Weight≅ 1 oz (28.3 g)


\*Minimum loop-power supply voltage equals the minimum sensor voltage 10VDC plus the voltage drop developed across all the other loop devices at 20mA.

# Appendix B - Dimensional Drawings



# Appendix C - Connection Diagrams





V = Voltage


L = LED

S = Undervoltage Setpoint

NO = Normally Open NC = Normally Closed


C = Common, Transfer Contact

### FIGURE 17 - ECS Series



I> = Overcurrent I< = Undercurrent Carrying Monitored Current Relay contacts are isolated.

## FIGURE 18 - ECSW Series



MC = Motor Contactor


M = Motor

F = Fuses OL = Overload

RSW = Reset Switch

FSW = Fan or Float Contacts CR = Control Relay

CS = Current Sensor MCC = Motor Contactor Coil



V = Voltage


I> = Adjustable Overcurrent

I< = Adjustable Undercurrent


W = Monitored Wire

ΔT - Adjustable Trip Delay

## FIGURE 19 - TCS Series



### FIGURE 20 - TCSA Series




PS = Power Supply

Z = Zero Adjust

S = Span Adjust

W = Insulated Wire Carrying Monitored Current PLC = PLC Analog Input or Meter Input



he insulated