THT CURRENT SENSE RANSFORMERS





- UL/C-UL recognized components
- 3000Vrms gate to drive winding test
- Useful operating frequency from 50kHz to 500kHz
- Most popular winding configurations

Electrical Specifications @ 25°C — Operating Temperature -40°C to 130°C										
Part ⁶ Number	Turns Ratio	Primary Inductance (1-10) (mH MIN)	DCR Pri (1-10) (Ω MAX)	DCR Sec1 (3-7) (m $\Omega \pm 15\%$)	DCR Sec2 (4-8) (mΩ $\pm 15\%$)	Hi-Pot (Pri-Sec) (Vrms)				
P0581	200:1:1	76	2.8	1.7	1.7	3000				
P0582	100:1:1	19	1.4	1.7	1.7	3000				
P0583	50:1:1	5	0.7	1.7	1.7	3000				


Additional Specifications										
Part Number		Reference	Calculation Data							
	RT	lpk (Amps)	Droop (%)	Max Flux Density	Kb	$egin{aligned} \mathbf{Req} \\ (m\Omega) \end{aligned}$				
P0581	200	34	1.00	2000	17.12	.9				
P0582	100	35	1.98	2000	68.49	.8				
P0583	15	36	1.19	2000	273.97	.75				

- NOTES: 1. These current sense transformers have two one turn primaries that can be used in parallel. The listed current ratings are for parallel connection.
 - 2. The reference values are for an application using the termination resistor (Rt) and operating with unipolar waveform at 100kHz, 40% duty cycle.
 - The estimated temperature rise is 55°C.


 3. The peak flux density should remain below 2100 Gauss to ensure that the core does not saturate. Use the following formula to calculate the peak flux density: Bpk = Kb * lpk * Rt * don/(Ff * Freq. in kHz) where: Rt is the terminating resistor in the application and Ff is 1 for unipolar waveform and 2 for bipolar waveform
- 4. To calculate the droop: Droop Exponent (D) = Rt * don/(Lpri in mH * Freq. in kHz) %Droop = $(1-e^{-D}) * 100$
- 5. The temperature rise of the component is calculated based on the total core loss and copper loss:
 - A. To calculate total copper loss (W): P(cu) = Ipk2 * Req * Ff * don where: Ff is 1 for unipolar waveform and 2 for bipolar waveform
 - (Bop in KG)^{2.532} where: Bop in kG = Kb * Ipk * Rt * don/(2000 * Freq. in kHz)^{1.67} * (Core Loss(W) + Copper Loss (W)). (Core Loss(W) + Copper Loss (W)). (Core Loss(W) + Copper Loss (W)). (Core Loss(W) + Copper Loss (W)).
- 6. To order RoHS compliant part, add the suffix "NL" to the part number (i.e. P0581 becomes P0581NL).

Mechanical

Schematic



SUGGESTED PCB HOLE PATTERN



Weight5 grams

Dimensions: Inches

Unless otherwise specified, all tolerances are $\pm \frac{.010}{0.25}$

For More Information:

Pulse Worldwide Headquarters 12220 World Trade Dr.

San Diego, CA 92128 U.S.A.

www.pulseeng.com TEL: 858 674 8100

FAX: 858 674 8262

Pulse Europe

Einsteinstrasse 1 D-71083 Herrenberg Germany

Tel: 49 7032 7806 116 Fax: 49 7032 7806 135

Pulse China

No. 1 Industrial District Changan, Dongguan China

Pulse North China Headquarters Room 1503 XinYin Building No. 888 YiShan Rd. Shanghai 200233 China

Tel: 86 769 85538070 Tel: 86 21 54643211/2 Fax: 86 769 85538870 Fax: 86 21 54643210

Pulse South Asia

150 Kampong Ampat #07-01/02 KA Centre Singapore 368324

Tel: 65 6287 8998 Fax: 65 6280 0080

Pulse North Asia No. 26

Kao Ching Rd. Yang Mei Chen Taoyuan Hsien Taiwan, R. O. C. Tel: 886 3 4641811 Fax: 886 3 4641911

Performance warranty of products offered on this data sheet is limited to the parameters specified. Data is subject to change without notice. Other brand and product names mentioned herein may be trademarks or registered trademarks of their respective owners. © Copyright, 2006. Pulse Engineering, Inc. All rights reserved.

P516.B (11/06) www.pulseeng.com